
WORLD TRADE CENTER DEBRIS DISTANCE STUDY





DEBRIS NORTH TOWER



DEBRIS SOUTH TOWER

NOTE

NORTH TOWER WAS UNDAMAGED BY COLLAPSE OF SOUTH TOWER

DEBRIS RANGED FURTHER FROM NORTH TOWER COLLAPSE THAN SOUTH TOWER

DIAMETERS TAKEN FROM CENTER OF NORTH TOWER

Jeffrey Sandor Orling Architect 675 North Terrace Avenue Mount Vernon, NY 10552

PRELIMINARY